

Oil Field Environmental Incident Summary

Incident: 20140906164311 **Date/Time of Notice:** 09/06/2014 16:43

Responsible Party: Gold Spur Trucking LLC

Well Operator: XTO ENERGY INC.

Well Name: JOSEPH 11-1H

Field Name: INDIAN HILL

Well File #: 18949

Date Incident: 9/5/2014 **Time Incident:** 19:30

Facility ID Number:

County: MCKENZIE

Twp: 152 **Rng:** 102 **Sec:** 1 **Qtr:**

Location Description:

Submitted By: Kaylan Dirx

Received By:

Contact Person: Michael Harrell
8116 61st St NW
Lot 3
Stanley, ND 58784

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building:

Distance Nearest Water Well:

Type of Incident Truck Overflow

Release Contained in Dike Yes - On Facility Site

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil	2.5	Barrels				

Brine

Other

Description of Other Released Contaminant:

Inspected:

Written Report Received:

Clean Up Concluded:

Risk Evaluation:

None-spill was contained on location

Areal Extent:

Potential Environmental Impacts:

None-spill was contained on location.

Action Taken or Planned:

Pump was shut off to stop the spill. Responsible party is arranging clean up, which will take place once the One Call ticket is cleared.

Wastes Disposal Location: Unknown at this time.

Agencies Involved:**Updates**

Date: 9/26/2014

Status: Reviewed; O&G Lead

Author: Stockdill, Scott

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

According to the incident summary, this spill remained on location. NDIC retains oversight.